

Input polarity markings for KMD-5220

Issued 22 February 2011

Applicable models

This service bulletin applies only to model KMD-5220.

Issues with input polarity markings

In late 2010, the input polarity markings on the label for model KMD-5220 were erroneously reversed. The correct polarity is shown in the illustration *KMD-5220 polarity markings*. The polarity markings on the circuit board are correct. Also, the illustrations in the installation and operation guide supplied with the KMD-5220 are correct. It is anticipated this problem will be corrected in the first quarter of 2011.




Illustration 1 KMD-5220 polarity markings